


### Problem

Very high static charges are generated on the plastic web during the unwinding and rewinding process. This can cause various problems for converters and their customers, such as:

1. Unpleasant shocks to operators.
2. Dust attraction, leading to contaminated stock.
3. Poor quality wound reels which can be difficult to fit onto machines and may cause feed problems.



### Solution

The most effective solution is to position a Model 915 bar as shown under Option 1. However, if space constraints do not allow a Model 915 bar to be installed within 150 mm of the web, a Model 976 bar should be used as shown under Option 2.