

Plastic Blow Moulded Bottles

Pulsed DC System




Plastics > rigid blow moulded bottles
> ISSUE 2

Problem

Blow moulded plastic containers such as shampoo bottles can experience problems at the packing station such as:

1. The highly charged bottles attract dust, leading to unacceptable contamination of what is expected to be a clean product.
2. Increased production costs, due to additional cleaning at the pre-filling station.
3. Very unpleasant operator shocks (leading to operator discontent).



Solution

The positioning of a long range Model 976 Pulsed DC ionising bar as shown above resolves the problem.

Constant streams of ions neutralise the blow moulded bottles, the conveyor and the operators' bodies via their hands and arms which are regularly placed within the ionisation field.

The bars are typically mounted above the conveyor on a raised strip light gantry.

Products shown in this document may be covered by one or more patents, patents applied for and/or registered designs and/or trade marks. For further information please refer to our Head Office or visit www.meech.com.

Meech International

UK: +44 1993 706 700
Hungary: +36 27 535 075

USA: +1 330 564 2000
China: +86 21 6119 6725

Belgium: +32 8067 0204

email: sales@meech.com
web: www.meech.com

© Meech Static Eliminators Ltd 2010

